

Summary of Facility Information in the County of Lake

Owner Name and Address: Rowan Wilson and Dara Wilson 309 Culloyah Arlee MT 59821 Phone: (406) 745-4285

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2406788	Wilson Foods	US Highway 93 N	Arlee	59821	(406) 726-7777

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
10 / 10 Currently In Use	3320	11/1/1998 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
11 / 11 Currently In Use	3321	11/1/1998 07 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
12 / 12 Currently In Use	3322	11/1/1998 07 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
13 / S13 Currently In Use	4599	11/1/2001 04 / Ye	Diesel 4,000	Concrete Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Juanita M Daly PO Box 159 Big Arm MT 59910 Phone: (406) 846-5622

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2412285	Big Arm General Store	314 5th St	Big Arm	59910	(406) 849-5355

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
3 / 03 Currently In Use	3566	4/30/1998 08 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						
4 / 04 Currently In Use	3567	4/30/1998 08 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Charlo School Dist 7 J 405 2nd Ave E Charlo MT 59824 Phone: (406) 644-2207

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2402789	Charlo School Dist 7 J	405 2nd Ave E	Charlo	59824	(406) 644-2207

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
5 / S5 Currently In Use	611	7/1/1998 08 / Ye	Heating Oil 10,000	Unknown None	Flexible Plastic Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Coulter Automotive Inc S Main PO Box 97 Charlo MT 59824 Phone: (406) 644-2215

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404615	Coulter Automotive Inc	S Main PO Box 97	Charlo	59824	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	2281	7/1/1995 11 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <input type="radio"/>A <input checked="" type="radio"/>B <input type="radio"/>C <input type="radio"/>D <input type="radio"/>E <input type="radio"/>F <input type="radio"/>G <input type="radio"/>H <input type="radio"/>I <input type="radio"/>J <input type="radio"/>K <input type="radio"/>L </div> <div> <input type="radio"/>A <input checked="" type="radio"/>B <input type="radio"/>C <input type="radio"/>D <input type="radio"/>E <input type="radio"/>F <input type="radio"/>G <input type="radio"/>H <input type="radio"/>I <input type="radio"/>J <input type="radio"/>K <input type="radio"/>L </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	2282	7/1/1995 11 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <input type="radio"/>A <input checked="" type="radio"/>B <input type="radio"/>C <input type="radio"/>D <input type="radio"/>E <input type="radio"/>F <input type="radio"/>G <input type="radio"/>H <input type="radio"/>I <input type="radio"/>J <input type="radio"/>K <input type="radio"/>L </div> <div> <input type="radio"/>A <input checked="" type="radio"/>B <input type="radio"/>C <input type="radio"/>D <input type="radio"/>E <input type="radio"/>F <input type="radio"/>G <input type="radio"/>H <input type="radio"/>I <input type="radio"/>J <input type="radio"/>K <input type="radio"/>L </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Moiese Mercantile 4924 Highway 212 PO Box 501 Charlo MT 59824 Phone: (406) 644-2385

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2406382	Moiese Mercantile	4924 MT Highway 212	Charlo	59824	(406) 644-2385

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently In Use	3968	3/1/1999 07 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	<input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Standing Arrow Trading Post Inc PO Box 174 Elmo MT 59915 Phone: (406) 849-6100

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2403906	Standing Arrow Trading Post Inc	77070 US Highway 93	Elmo	59915	(406) 849-6100

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Temporarily Out of Use	3999	5/1/1995 11 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A●●DEFGHIJKL</div> <div>BDEFGHI●K L</div> </div>	Yes Yes Yes Yes
4 / 04 Temporarily Out of Use	4000	5/1/1995 11 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A●●DEFGHIJKL</div> <div>BDEFGHI●K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Ronan School District No 30 421 Andrew NW Ronan MT 59864 Phone: (406) 644-2448

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404823	Pablo Elementary School	608 4th Ave	Pablo	59855	(406) 676-3390

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
1 / S1 Currently in Use	1903	4/28/1966 40 / No	Heating Oil 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Joes Jiffy Stop Inc PO Box 277 Pablo MT 59855 Phone: (406) 676-3570

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2411124	Quicksilver Express	52001 US Highway 93	Pablo	59855	(406) 695-5000

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3296	1/1/1987 19 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3297	1/1/1987 19 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B <input checked="" type="radio"/> C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3298	1/1/1987 19 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B <input checked="" type="radio"/> C <input checked="" type="radio"/> D E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Confederated Salish & Kootenai Tribe
PO Box 278 Pablo MT 59855 Phone: (406) 675-2700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2412096	Two Eagle River School	52096 US Highway 93	Pablo	59855	(406) 675-0292

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently in Use		12/29/1988 17 / No	Heating Oil 12,000	STI-P3 Double-Walled	Unknown None	Not Listed	<div> A B C D <input checked="" type="radio"/> F G H I J K L </div> <div> B D E F G H I J K <input checked="" type="radio"/> </div>	No Yes Yes No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Mission Valley Concrete Ind Inc PO Box 395 Pablo MT 59855 Phone: (406) 675-4500

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2413438	Mission Valley Concrete Ind Inc Old US 9	Old US Highway 93 S	Pablo	59855	(406) 675-4500

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1651	3/1/1994 12 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A●●●●EFGHIJKL</div> <div>BDEFGHI●K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1652	3/1/1994 12 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A●●●●EFGHIJKL</div> <div>BDEFGHI●K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1653	3/1/1994 12 / No	Diesel 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>●●●●EFGHIJKL</div> <div>BDEFGHI●K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: University of Montana Physical Plant Bldg 32 Missoula MT 59812 Phone: (406) 982-3303

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2400507	U of M Flathead Lake Biological Station	311 Bio Station Ln	Polson	59860	(406) 982-3202

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 05 Currently in Use	2185	3/15/1991 15 / No	Gasoline 1,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / S6 Currently in Use	2186	3/15/1991 15 / No	Heating Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Polson School District 23 111 4th Ave E Polson MT 59860 Phone: (406) 883-6333

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2402867	Cherry Valley School	107 8th Ave W	Polson	59860	(406) 883-6329

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / S2 Currently in Use	1805	8/1/1990 15 / No	Heating Oil 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404560	Mountain West Co Op Polson	808 Main St	Polson	59860	(406) 883-5600

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	4155	1/1/2000 06 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4156	1/1/2000 06 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4741	1/1/2000 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently In Use	4648	1/1/2000 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Confederated Salish & Kootenai Tribe
PO Box 278 Pablo MT 59855 Phone: (406) 675-2700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404836	Outlaw Saddlery	316 1st St E	Polson	59860	(406) 883-6822

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently in Use		5/22/1966 40 / No	Heating Oil 400	Asphalt Coated or Bare Steel None	Unknown None	Not Listed	<div> A B C D E F G H I J K L </div> <div> B D E F G H I J K L </div>	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: George & Ramona Mahoney PO Box 1127 Polson MT 59860 Phone: (406) 883-6851

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2405770	Polson Bay Grocery 425	1406 US Highway 93 S	Polson	59860	(406) 883-6851

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently In Use	4664	5/23/2002 04 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
5 / 05 Currently In Use	4665	5/23/2002 04 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
6 / 06 Currently In Use	4666	5/23/2002 04 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
7 / 07 Currently In Use	4667	5/23/2002 04 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Pier 93 9 2nd Ave W Polson MT 59860 Phone: (406) 883-5768

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2405957	Pier 93	9 2nd Ave W	Polson	59860	(406) 883-5768

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 01 Currently in Use	1802	4/23/1986 20 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 02 Currently in Use	1803	4/23/1986 20 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1804	11/1/1990 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

<p align="center">Summary of Facility Information in the County of Lake</p>
--

Owner Name and Address:	Grits Inc	65811 US Highway 93	Polson	MT	59860	Phone: (406) 883-3861
--------------------------------	-----------	---------------------	--------	----	-------	-----------------------

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2407247	Jette Store	65811 US Highway 93	Polson	59860	(406) 883-3861

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently in Use	1215	4/1/1996 10 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	●	E	F	G	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	●	E	F	G	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
5 / 05 Currently in Use	1216	4/1/1996 10 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	●	E	F	G	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	●	E	F	G	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
6 / 06 Currently in Use	1217	4/1/1996 10 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	●	E	F	G	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	●	E	F	G	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2408717	Town Pump Inc Polson	1714 US Highway 93 E	Polson	59860	(406) 883-9445

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	2490	9/1/1982 23 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
2 / 02 Currently in Use	2491	9/1/1982 23 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
3 / 03 Currently in Use	2492	9/1/1982 23 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
4 / 04 Currently in Use	2493	9/1/1982 23 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
5 / 05 Currently in Use	2494	9/1/1982 23 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
11 / 11 Currently In Use	4819	10/24/2002 03 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
12 / 12 Currently In Use	4820	10/24/2002 03 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: City of Polson 106 1st St E Polson MT 59860 Phone: (406) 883-2131

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2411824	Polson Country Club	111 Bayview Dr	Polson	59860	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	647	8/14/1990 15 / No	Gasoline 500	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	<div style="display: flex; flex-wrap: wrap; gap: 2px;"> (A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L) </div> <div style="display: flex; flex-wrap: wrap; gap: 2px;"> (B)(D)(E)(F)(G)(H)(I)(J)(K)(L) </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Confederated Salish & Kootenai Tribe
PO Box 278 Pablo MT 59855 Phone: (406) 675-2700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613869	KwaTaqNuk Resort	303 2nd Ave E	Polson	59860	(406) 883-3636

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use		5/1/1991 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Marcia Harris PO Box 630223 Ravalli MT 59863 Phone: (406) 745-3866

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2409997	Ravalli Store	205 Buffalo St	Ravalli	59863	(406) 745-4554

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3464	9/1/1989 16 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3465	9/1/1989 16 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3466	9/1/1989 16 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Saint Luke Hospital 107 6th Ave SW Ronan MT 59864 Phone: (406) 676-4441

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2403736	Mission Mountain Medicine Ronan	107 6th Ave Sw	Ronan	59864	(406) 676-4441

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
3 / S3 Currently In Use	4369	11/1/1999 06 / Ye	Diesel 2,000	Unknown None	Copper Double-Walled/Non-Corro	Pressurized	<div> <div>A B C D E F G H I <input checked="" type="radio"/> K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F G H I <input checked="" type="radio"/> K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404530	Mountain West Co Op Ronan	1408 US Highway 93 S	Ronan	59864	(406) 676-2201

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
9 / 09 Currently In Use	2829	5/1/1997 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div>(A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div> <div>(B)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div>	Yes Yes Yes Yes
10 / 10 Currently In Use	2830	5/1/1997 09 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div>(A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div> <div>(B)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div>	Yes Yes Yes Yes
11 / 11 Currently In Use	2831	5/1/1997 09 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div>(A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div> <div>(B)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div>	Yes Yes Yes Yes
12 / 12 Currently In Use	2832	5/1/1997 09 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div>(A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div> <div>(B)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div>	Yes Yes Yes Yes
13 / 13 Currently In Use	2833	5/1/1997 09 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div>(A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div> <div>(B)(D)(E)(F)(G)(H)(I)(J)(K)(L)</div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Lake County Joint Airport Board 106 4th Ave E Polson MT 59860 Phone: (406) 883-7214

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404649	Ronan Airport	2200 Old US Highway 93	Ronan	59864	(406) 676-3461

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
2 / 02 Currently In Use	3984	4/1/1999 07 / No	Kerosene 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
3 / 03 Currently In Use	3985	4/1/1999 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes	
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	<input checked="" type="radio"/>		<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Ronan School District No 30 421 Andrew NW Ronan MT 59864 Phone: (406) 644-2448

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2404824	East of Ronan Middle School	200 Round Butte Road E	Ronan	59864	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / S5 Currently in Use	1904	8/1/1996 09 / No	Heating Oil 10,000	Fiberglass Reinforced Plastic None	Copper Double-Walled/Non-Corro	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Arnies Gas and Tire Center Inc 9 US Highway 93 S Ronan MT 59864 Phone: (406) 676-0400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2405517	Arnies Gas and Tire Center Inc	9 US Highway 93 S	Ronan	59864	(406) 676-0400

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 04 Currently In Use	3888	5/7/1978 28 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
5 / 03 Currently in Use	3889	5/8/1971 35 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
6 / 02 Currently in Use	3890	5/8/1971 35 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
7 / 01 Currently in Use	3891	5/8/1971 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Joes Jiffy Stop Inc PO Box 277 Pablo MT 59855 Phone: (406) 676-3570

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2405768	Dyno Mart	303 US Highway 93 N	Ronan	59864	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently In Use	1317	4/1/1992 14 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 01 Currently In Use	1315	11/13/1984 21 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 02 Currently In Use	1316	11/13/1984 21 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Johns Fuel Farm Inc 308 US Highway 93 S Ronan MT 59864 Phone: (406) 676-3461

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2407437	Johns Fuel Farm Inc	308 US Highway 93 S	Ronan	59864	(406) 676-3461

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	3394	4/23/1961 45 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
2 / 02 Currently in Use	3395	4/23/1961 45 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
3 / 04 Currently in Use	3397	4/24/1971 35 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
4 / 05 Currently in Use	3398	4/24/1971 35 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
5 / 06 Currently in Use	3399	4/23/1961 45 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
11 / 03 Currently in Use	3396	4/24/1971 35 / No	Heating Oil 8,000	Fiberglass Reinforced Plastic None	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: George Atkinson 1018 US Highway 93 S Ronan MT 59864 Phone: (406) 676-4280

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2407532	Georges BP UST	1018 US Highway 93 S	Ronan	59864	(406) 676-4280

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
2 / 11	400	4/1/1994	Diesel	Composite (Steel w/ FRP)	Fiberglass Reinforced Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
Temporarily Out of Use		12 / No	10,000	None	None		<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes												
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
12 / 12	401	7/1/1997	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
Temporarily Out of Use		09 / No	8,000	None	None		<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes												
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
13 / 13	402	7/1/1997	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
Temporarily Out of Use		09 / No	8,000	None	None		<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes												
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
14 / 14	403	7/1/1997	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
Temporarily Out of Use		09 / No	10,000	None	None		<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes												
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
15 / 15	404	7/1/1997	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
Temporarily Out of Use		09 / No	12,000	None	None		<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes												
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
16 / 16	405	7/1/1997	Gasoline	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					
Temporarily Out of Use		09 / No	15,000	None	None		<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	Yes Yes Yes												
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Jiffy Stop Inc 51356 Highway 93 Ronan MT 59864 Phone: (406) 675-3570

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2407562	Joes Jiffy Stop	51356 US Highway 93	Ronan	59864	(406) 676-3570

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	1269	10/4/1990 15 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	1270	10/4/1990 15 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1271	10/4/1990 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2408718	Town Pump Inc Ronan	1213 29th St	Ronan	59864	(406) 656-5290

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4822	4/14/1972 34 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	4823	4/14/1972 34 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	4824	4/14/1972 34 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	4825	4/14/1980 26 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Confederated Salish & Kootenai Tribe
PO Box 278 Pablo MT 59855 Phone: (406) 675-2700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2410386	Kicking Horse Job Corps Center	2000 Mollman Pass Trl	Ronan	59864	(406) 644-2217

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Over/C
1 / 14 Currently in Use		3/27/1995 11 / No	Diesel 1,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<div> <input checked="" type="radio"/> A <input checked="" type="radio"/> B <input checked="" type="radio"/> C <input checked="" type="radio"/> D <input checked="" type="radio"/> E <input checked="" type="radio"/> F <input checked="" type="radio"/> G <input checked="" type="radio"/> H <input checked="" type="radio"/> I <input checked="" type="radio"/> J <input checked="" type="radio"/> K <input checked="" type="radio"/> L </div>	No Yes Yes Yes
2 / 15 Currently in Use		3/27/1995 11 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<div> <input checked="" type="radio"/> A <input checked="" type="radio"/> B <input checked="" type="radio"/> C <input checked="" type="radio"/> D <input checked="" type="radio"/> E <input checked="" type="radio"/> F <input checked="" type="radio"/> G <input checked="" type="radio"/> H <input checked="" type="radio"/> I <input checked="" type="radio"/> J <input checked="" type="radio"/> K <input checked="" type="radio"/> L </div>	No Yes Yes Yes
3 / 13 Currently in Use		3/27/1995 11 / No	Diesel 1,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	U.S. Suction	<div> <input checked="" type="radio"/> A <input checked="" type="radio"/> B <input checked="" type="radio"/> C <input checked="" type="radio"/> D <input checked="" type="radio"/> E <input checked="" type="radio"/> F <input checked="" type="radio"/> G <input checked="" type="radio"/> H <input checked="" type="radio"/> I <input checked="" type="radio"/> J <input checked="" type="radio"/> K <input checked="" type="radio"/> L </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: School District 28 PO Box 1540 Saint Ignatius MT 59865 Phone: (406) 745-3811

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2403762	Saint Ignatius School	4th & Blaine St	Saint Ignatius	59865	(406) 745-3811

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently In Use	4563	6/1/1997 09 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2405769	Allards General Store 447	US Highway 93 N	Saint Ignatius	59865	(406) 745-9192

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently in Use	5042	12/1/2005 00 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
5 / 05 Currently in Use	5043	12/1/2005 00 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	<input checked="" type="radio"/>	K	L		B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
	B		D	E	F	G	H	I	J	K	<input checked="" type="radio"/>																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Lake

Owner Name and Address: Morton & Coffman LLC Box 507 Saint Ignatius MT 59865 Phone: (406) 745-3634

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2410647	Stuarts Service Center Inc	240 Mountain View Dr	Saint Ignatius	59865	(406) 745-3696

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 06 Currently in Use	4595	5/1/1995 11 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 07 Currently in Use	4596	5/1/1995 11 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 08 Currently in Use	4597	5/1/1995 11 / No	Diesel 6,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed